



123 Example Street, Nelson
7010 New Zealand

Inspection date

2 Jun 2022

Performed by

Dan Propgometry

Inspection type

Routine report

Table of Contents

Summary	Page 1
Front yard	Page 2
Deck	Page 4
Lounge	Page 5
Kitchen	Page 6
Bathroom	Page 8
Bedroom	Page 9
Hallway	Page 10
Study	Page 11
Bedroom 2	Page 12
Backyard	Page 13
Meter read	Page 14
Signatures	Page 15
Appendix 1: Maintenance TODOs	Page 16

Summary

People

Landlords: Jenny jackson and Sam ooden

Tenant: Tessa tenant

Summary notes

Thanks for looking after the place guys! I've noted a few things for me to do and couple for you. Any questions be sure to let me know :) — Jenny

Space	No issues	Requires attention
Front yard	✓	
Deck	✓	
Lounge	✓	
Kitchen		!
Bathroom	✓	
Bedroom	✓	
Hallway	✓	
Study	✓	
Bedroom 2	✓	
Backyard	✓	
Meter read	✓	

The digital version of this report and all images and/or videos can be found [here on myInspections.com](#).

Front yard

✓ No issues


Notes

Lawns and garden look well maintained (thank you). Stairs appear to be in good working condition.


To-do's

- Investigate non-slip solutions for stairs
- Organise tree trimming for next month (landlord)

Photos & Videos



[1 of 2](#)



[2 of 2](#)

Front yard (continued)

Review by Tessa tenant

Notes

Hi Jenny, as we discussed during the inspection, the trash bins need to be replaced.


Deck

✓ No issues

Notes

Deck is in good condition. Reminder for me (landlord) to reseal the deck in 6 months time. I'll assess again at next inspection.

Photos & Videos



[1 of 1](#)

Lounge

✓ No issues


Notes

Chipped tile in front of fireplace


To-do's

- Clean heat pump filter next inspection

Photos & Videos




[1 of 4](#)



[2 of 4](#)



[3 of 4](#)



[4 of 4](#)

Chip on tile in front of fireplace

Kitchen

⚠ Requires attention


Notes

Oven seal needs replacing. Wear and tear on sink edge. Overall great condition!


To-do's

- Replace oven seal

Photos & Videos



[1 of 6](#)



[2 of 6](#)

Oven seal needs replacing. Door sits open.



[3 of 6](#)

Kitchen (continued)




[4 of 6](#)



[5 of 6](#)

Pre-existing scratches on the cupboard



[6 of 6](#)

Bathroom

✓ No issues


Notes

Bathroom is in good condition, last regROUTED 2 months ago


Photos & Videos




[1 of 6](#)




[2 of 6](#)




[3 of 6](#)



[4 of 6](#)



[5 of 6](#)



[6 of 6](#)


Bedroom

✔ No issues


Notes

Clean and tidy.

Photos & Videos



[1 of 2](#)



[2 of 2](#)

Hallway

✓ No issues


Notes

Few scuffs on skirtings but is general wear and tear. Smoke alarm checked and working.

Photos & Videos



[1 of 2](#)



[2 of 2](#)


Study

✓ No issues

Notes

Good condition. Stain on carpet in front of cupboards.

Photos & Videos



[1 of 4](#)



[2 of 4](#)



[3 of 4](#)



[4 of 4](#)

Stain on carpet


Bedroom 2

✔ No issues


Notes

A small stain was visible last inspection but since has been cleaned.

Photos & Videos



[1 of 2](#)



[2 of 2](#)

Backyard

✓ No issues

Notes

Lawns and garden are tidy and well maintained/presented

Photos & Videos



[1 of 3](#)



[2 of 3](#)



[3 of 3](#)

Meter read

✔ No issues

Photos & Videos



[1 of 1](#)

Meter

Signatures

Jenny jackson

LANDLORD

A handwritten signature in blue ink, appearing to read 'Jenny Jackson', written in a cursive style.

Date: 21 Oct 2024

Sam ooden


LANDLORD

A handwritten signature in blue ink, appearing to read 'Sam Ooden', written in a cursive style.

Date: 21 Oct 2024

Tessa tenant

TENANT

A handwritten signature in blue ink, appearing to read 'Tessa Tenant', written in a cursive style.

Date: 21 Oct 2024

Appendix 1: Maintenance to-do's

Property: 123 Example Street, Nelson 7010 New Zealand

The following maintenance to-do's were flagged during this inspection:

Front yard

- Investigate non-slip solutions for stairs
- Organise tree trimming for next month (landlord)

Lounge

- Clean heat pump filter next inspection

Kitchen

- Replace oven seal